

TO BE FILLED BY THE INSPECTING OFFICER
(ASSISTANT ENGINEER)

1 Name of officer **PRIYA R.R.**
 2 Name of School **AMRUTHA VIDHYALAYAM**
 3 Location with name of education district/Sub district **CHERUTHURUTHY/CHAVAKKAD/WADAKKANCHERY**

4 Classification of building and size

RCC ROOF		PERMANENT TILE ROOF	
7.40X6.60X3.60M	8NOS(GF)	7.40X6.60X3.60M	8NOS(SF)
7.40X6.60X3.60M	8NOS(FF)	7.40X6.60X3.60M	8NOSTF)
		Total	32 Nos
Extension Building - Level Difference Ground floor		Ground floor	
7.21x7.00x3.60	GF	3.59x7.00x3.60	Guest room
7.41x7.00x4.27	GF	3.58x7.00x3.60	Room
7.3x7.00x4.27	GF	7.33x7.00x3.60	Class room
		7.25 x7.00x4.48	Class room
		7.39x7.00x4.48	Class room
First Floor		Second Floor	
7.35x7.00x3.60	Class room	7.35x7.00x3.60	Class room
7.33x7.00x3.60	Class room	7.33x7.00x3.60	Class room
7.25x7.00x3.60	Class room	7.25x7.00x3.60	Class room
7.39x7.00x3.60	Class room	7.39x7.00x3.60	Class room
Third Floor			
7.35x7.00x3.60	Class room		
22.34x7.00x3.60	Class room		

5 Period which certificate issued **2023-24**
 6 Nature of Defect if any **NIL**
 a) Foundation
 b) Super structure
 c) Doors and windows
 d) Wood work wrought and put up **Nil**
 e) Roof
 f) Flooring
 g) Miscellaneous
 7 Any major defects notices which will render the building unsafe if any manner **Nil**
 8 Whether maintenance work have been done properly **Yes**
 9 Whether structure is sound enough or not for conducting classes **Sound enough under normal weather and wind condition**

Note: The stability of the structure should be examined also with reference to location altitude internsity of wind exposure to flood etc

Any additional observation deemed necessary for the certificate may be furnished seperately with the certificate

Certificate that the School was inspected by me on 13/09/2023 and found Fit to conduct classes for the period for the reason stated above

VALLATHOL NAGAR
13/09/2023

Signature

Asst. Engineer
L. S. G. D. Section
Vallathol Nagar Grama Panchayath